

Date: March 21, 2016
Subject: Discontinuation of Johnson FX10 Controllers
From: TarpLess Ripening Room Technical Support Team
To: All Facilities using Johnson FX10 Controllers.

Item: Discontinuation of Johnson FX10 Controllers

As of 2015, Johnson Controls has discontinued production of all Legacy FX field controllers and accessories.

It is therefore recommended that installations using Johnson FX10 controllers retrofit to the new, more advanced PLC control system to ensure continued technical support as well as access to parts and service.

Every effort will be made to continue support of FX10 controllers until all retrofits to the new system are complete.

For questions or to schedule a retrofit to the new PLC control system, Please contact:

George Thistle , Technical Service & Support
803-691-8000, ext 102
gthistle@thermaltechnologies.com

David Byrne , Vice President, Sales
803-461-7980
dbyrne@thermaltechnologies.com

James R. Lentz, President
803-691-8000
jlentz@thermaltechnologies.com

Thank You.