

Date: November 11, 2016
Subject: Discontinuation of BRC Ripening Room Controllers
From: TarpLess Ripening Room Technical Support Team
To: All Facilities using BRC Controllers.

Item: Discontinuation of BRC Ripening Room Controllers

Due to advances in control systems technology, key components of BRC ripening room controllers are no longer being manufactured by their suppliers.

It is therefore recommended that installations using BRC controllers retrofit to the new more advanced PLC control system to ensure continued technical support as well as access to parts and service.

BRC components are being reconditioned as possible for reuse. These components will be available as "used" parts while supplies last. Every effort will be made to continue support of the BRC until all retrofits to the new system are complete.

For questions or to schedule a retrofit to the new PLC control system, Please contact:

George Thistle , Technical Service & Support
803-691-8000, ext 102
gthistle@thermaltechnologies.com

David Byrne , Vice President, Sales
803-461-7980
dbyrne@thermaltechnologies.com

James R. Lentz, President
803-691-8000
jlentz@thermaltechnologies.com

Thank You.